

---

**Certificate of Test Conformance Number: 103694 Issue 1**

---

**Customer Name & Address:** Lazer Lamps  
Units 1 & 2  
Harlow Mill Business Centre  
Essex  
CM20 2FD

**Customer Order Number:** 0859

**Test Item(s) Receipt Date:** 18<sup>th</sup> July 2019

**Test Item(s) Description:** Heavy Duty Work Lamp

**Test Item(s) Part Number(s):** Utility 25

**Test Item(s) Serial Number(s):** #1 & #2

**Test Item(s) Quantity:** 2

**Reference Standard(s):** DIN 40 050 Part 9: Road Vehicle Degrees of Protection

**Applied Test(s):** IP6Kx, IPx9K

**Test Date(s):** 18<sup>th</sup> to 23<sup>rd</sup> July 2019

**Test Results:** The detailed tests were performed in accordance with the requirements of the defined environmental test standards.

Lamp #1 was subjected to the IPx9K water test.

Lamp #2 was subjected to the IP6Kx dust test.

On completion of the tests, no water or dust ingress was observed within the enclosures.

Therefore, Lamp #1 conformed to the requirements of the IPx9K rating and Lamp #2 conformed to the requirements of the IP6Kx rating.

**Author:**



Paul Lee  
Test Lab Manager

**Approval:**



Steve Drane  
Service Manager

**Issue Date:**

24<sup>th</sup> July 2019

*The results detailed herein relate only to the test item(s) submitted for testing.*